

# Memo

To: Distribution

From: J. Scott

Date: January 10, 2006

Re: Safety Walk

---

On January 10, 2006 a facility Risk Analysis (FRA-8-06) and a Safety Walk through of starting the Siemens Motor Generator for operations were performed. The tasks observed included startup prerequisites, racking in the 52 breaker, and startup of MG set.

## Safety Walk Attendees:

J. Scott (ESHQ)

M. Bannon (C-A WOSH Representative)

R. Bonati (Power Group Engineer)

C. Watts (Power Group Operator)

J. Famiglietti ( Power Group Operator)

## Positive Observations:

1. Use of NFPE 70E PPE for racking in 52B breaker and procedures followed.
2. A checklist and procedure used correctly for all operations.
3. Supervisor used a handwritten checklist to note and correct extra steps caused by the extended shutdown AC power reduction. Limited any impact on generator routine shutdown.

## Negative Observations:

1. No negative observations of these tasks noted.

2. Operator had a suggestion to install resistive heating devices in place of portable heaters used. Should investigate if this is feasible.

Distribution: Safety Walk Attendees

R. Karol

E. Lessard

D. Lowenstein

J. Sandberg

D. Passarello